

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No.

Dated: 19/01/2026

It is certified that an inspection team headed by PHC- HUNAGUND TEAM

14/01/2026 [&] 14/01/2026 _{from} inspected the

DREPUNG GOMANG SCHOOL on request based upon the water testing report and

inspection of the school premises, the potable water is safe for students and staff and school is

having good hygiene. It is also having provision for running water in the toilets and also

maintains the hygienic sanitation condition in the school building & the campus as per norms

prescribed by the Central/State/ U.T. Govt.

The above is valid for a period of extended time.

Signature with Seal

Name: DR. NARENDRA PAWAR

Designation: THO

Name & Address of the
Office/Department:

TALUKA HEALTH OFFICE
MUNDAGOD

To,
Drepung Gomang School
Lama Camp No.2, P.O. Tibetan Colony
Mundgod 581411, Uttara Kannada
Karnataka State

Note: The certificate is to be issued by authorized officer/PHED Lab/local bodies

Water Sample Report.

ಅ.ಕ್ರ. ಸಂ.	ಉಪ ಕೇಂದ್ರದ ಹೆಸರು	ಗ್ರಾಮ ಪಂಚಾಯತ್ ಹೆಸರು	ಗ್ರಾಮದ ಹೆಸರು	ನೀರಿನ ಮಾದರಿ ಸಂಗ್ರಹಿಸಿದವರ ಹೆಸರು & ಪದನಾಮ	ನೀರಿನ ಮಾದರಿ ಸಂಗ್ರಹಿಸಿದ ವಿಳಾಸ	ನೀರಿನ ಮಾದರಿ	ನೀರಿನ ಮೂಲ	ಸಂಗ್ರಹಿಸಿದ Date & Time		ಪ್ರಯೋಗಾಲಯಕ್ಕೆ ತಲುಪಿಸಿದ Date & Time		ಪರಿಶೀಲನೆ
1	TATTIHALI II	NANDIKATT - A	Comp-6	MANJULA PSE	DREPUNG	MANU	BORE	15/11/26	11:30 AM	15/11/26	1pm	SPP
2				CHO	GUMANG	TANK	WELL					
3					SCHOOL							
4												
5	TATTIHALI II	NANDIKATT - A	CAMP -6	MANJULA PSE	DREPUNG	RO	BORE	12/11/26	12pm	12/11/26	1pm	SPP
6				PSE	GUMANG	WATER	WELL					
7				CHO	SCHOOL							


 ವೈದ್ಯಾಧಿಕಾರಿಗಳು,
 ಪ್ರಾಥಮಿಕ ಆರೋಗ್ಯ ಕೇಂದ್ರ,
 ಹುಣಸೂರು. ಜಿಲ್ಲೆ ಮುಂಡಗೋಡೆ. (ಹಾ.ನಂ.)